

## IDDE Summary

Wareham – as of 30 June 2023

Category	Task	Status	Cumulative Results
IDDE	Rank outfalls/interconnections	Needs review	536 total outfalls including road cuts and culverts
Mapping	Outfalls and rough catchment	Mostly complete	
Mapping	Identify interconnections	Needs work	None identified
Mapping	Receiving waters and pollutants association with outfalls	Complete	See GIS and AGOL
Mapping	Identify treatment systems (BMPs)	Progressing	136 Town owned
Mapping	Catchbasins, Manholes and Pipes	Progressing	updated with investigations
Dry weather inventory	Inspect Outfalls/Interconnections for dry weather flows	Needs work	112 complete 36 dry weather samples
Wet weather sampling	Sample stormwater at high and low priority outfalls	Needs work	57 / 364 complete
Catchment Investigation	Catchment investigation for all MS4 outfalls	Needs work	111 / 132 complete
Mapping	Update catchments based on mapping	Too soon to start	

### MS4 Outfalls: 536 total in urbanized area that are town owned

329 outfall pipes, 200 road cuts, 2 simple culverts, 2 stormwater culverts, 3 treatment outlets

172 excluded, 195 high priority, 169 low priority

**MS4 Year 2023 (July 2022 – June 2023)** - Wareham's continued support of the Collaborative has resulted in great progress this year with 53 outfall inventories, 1 dry weather samples, 21 stormwater samples, and 67 catchment investigations with the trailer. FY23 and FY24 has seen a high level of investment in Wareham's IDDE efforts and as a result the town is making good progress in a daunting IDDE requirement.

**ArcGIS Online Map:** [Web Map Link](#)